



CHAIN OF CUSTODY RECORD

STEWART ENVIRONMENTAL CONSULTANTS, INC.
3801 Automation Way, Suite 200, Fort Collins, CO 80525

Batch: 67a1

Telephone: (970) 226-5500
Facsimile: (970) 226-4946

PAGE 1 OF 1

SEC-USE ONLY		CLIENT: Steve Ted Sord - Meadow Mountain				SAMPLER		
Client No.	Sample No.	SAMPLE COLLECTION INFO		CLIENT SAMPLE IDENTIFICATION	Matrix Type	QC Report Needed	Total No. of Cont.	Name: STEPHEN L. (12/13/04)
		Date	Time	Grab / Comp				Signature: <i>[Signature]</i>
S10-	505	2-1-10	6:30 AM	G	1 Plant	DW	N	510 032 1310
	508	2-1-10	6:30 AM		2			
	508	2-1-10	6:30 AM		3			
	BOC 524	2-1-10	6:30 AM		4			510 032 1254
	BOC 524	2-1-10	6:30 AM		5			510 032 1310
	BOC 524	2-1-10	6:30 AM		6			
	631	2-1-10	6:30 AM		7			
	549	2-1-10	6:30 AM		8			
	525	2-1-10	6:30 AM		9			
	Nitrate	2-1-10	6:30 AM		10			510 032 1256
	515.4	2-1-10	6:30 AM		11			510 032 1310
	548	2-1-10	6:30 AM		12			
	504	2-1-10	6:30 AM		13			
	504	2-1-10	6:30 AM		14		2	

Compliance samples may require you to report the temperature of samples as they arrive in the laboratory. Would you like the temperature of samples recorded upon receipt by the laboratory? Please check Yes: record and report temperature. No: temperature not requested.

Leaving this field blank implies that the incoming temperature is not requested.

RELINQUISHED BY	DATE / TIME	Received by	Date / Time	REQUESTED COMPLETION DATE	REPORT TO:	PHONE:	FAX:
<i>[Signature]</i>	2/1/10	M. Flanagan	2-1-10 11:15				
Relinquished by	Date / Time	Received by	Date / Time	MATRIX TYPE WW = waste water DW = drinking water L = Liquid S = soil A = Air	CLIENT:	ADDRESS:	CITY, STATE ZIP:
Relinquished by	Date / Time	Received by	Date / Time	SL = sludge SD = Solid CDPHE REPORT REQUIRED	INVOICE TO:	ADDRESS:	CITY, STATE ZIP:
Database Entry By <i>[Signature]</i>	Date	2-1-10		PWSID #	ADDRESS:	CITY, STATE ZIP:	